

Subject: Blower Motor Fan Blade Spacer Service Pack
Date: 10/25/21
Regions: Global
Models Affected: HHC 90X, HC 4, HC 5, HC 15



Summary

Service packs 182498-001 and 182498-002 now include spacers. These instructions, included in the service pack, clarify which spacer to use with which blower motor.

When replacing a blower motor, the replacement part may be from one of several different manufacturers. Depending on the blower motor you receive, you may need to install the blower motor using one of two different spacers, or none.

Two different spacers are included in with the Service Pack, but if necessary, you will only use one, never two, and then discard one or both as applicable. Refer to the table below to determine which spacer to use.

IMPORTANT: Using the wrong spacer may cause vibration, noise, and damage to the blower motor.

Part # 25751 / 25752 Motor Manufacturer	Motor Ring Clip?	Spacer #	Spacer Image
ALTRAN	NO	ME50-097 OD = .313 in (7.95 mm)	
FASCO	NO	25768 OD = .375 in. (9.52 mm)	
A.O. SMITH	NO		
BAY PRODUCTS	YES	NONE	No Spacer Required

Warranty

Service Pack includes a 90-day parts warranty from the date of install.

Questions

For further information, please contact Technical Services using one of the following options:

Email: technicalservices@hennypenny.com

Call:

- U.S. and Canada: +1-800-417-8405
- Global: +1-937-456-8405

Text: +1-937-456-8405

[Live chat](#) via the Henny Penny website, extranet, or customer support website.