

Subject: FlexFusion Ignition Module Cable Bulletin
Date: 09/01/21
Region: Global
Models Affected: FlexFusion Gas Combi

Summary

Ignition modules P/Ns MM10017376 and MM10017377 now include, both a combustion blower cable and ignition module. Service providers must now replace the combustion blower cable when replacing the ignition module.

IMPORTANT: Failure to replace the combustion blower cable may result in permanent ignition module damage and error code(s) presented on the oven control panel. A label has been added to the ignition module packaging stating that the combustion blower cable must be replaced along with the module.

Part Ordering Requirement

For existing parts stock of MM10017376 and MM10017377, that do not include a combustion blower cable, the cable should be ordered separately to supplement. The combustion blower cable part number is MM10014077.

Part Numbers

Order the following stock.

Part #	Description	Stocking Level
MM10017376	Ignition Module with Blower Cable, 230 VAC	B
MM10017377	Ignition Module with Blower Cable, 120 VAC	B
MM10014077	Combustion Blower Cable	

Warranty

Parts includes a 90-day parts warranty from the date of install.

Questions

For further information, please contact Technical Services using one of the following options:

Email: technicalservices@hennypenny.com

Call:

- U.S. and Canada: +1-800-417-8405
- Global: +1-937-456-8405

Text: +1-937-456-8405

[Live chat](#) via the Henny Penny website, extranet, or customer support website.