

Subject: EEG and LVG Pilot and Flame Sensor Bulletin
Date: 09/01/21
Region: Global
Models Affected: EEG and LVG Fryers

Summary

In 2014, Henny Penny improved the pilot design for EEG and LVG open fryers. At that time, service providers were instructed to use pilot kits P/Ns 140296 (NG) or 140297 (LP) for replacement parts. The old design pilot P/N 75854 and flame sensor P/N 76978 continued to be sold as service parts since the pilot kits were not yet approved for all countries. Please see the attached Tech News bulletin from 2014 for reference.

<p>OBS</p>		
	<p>75854</p>	<p>76978</p>
<p>CURRENT</p>		
	<p>140296 (NG)</p>	<p>140297 (LP)</p>

Once all inventory is exhausted, Henny Penny will obsolete the old design pilot P/N 75854 and flame sensor P/N 76978 and they will no longer be available to order or return. Distributor stock will continue to be warranted for 90-days after installation.

For all future pilot replacement service on EEG and LVG fryers, use pilot kits P/Ns 140296 (NG) or 140297 (LP) exclusively. These pilot kits are approved for use globally including Russia, New Zealand, and Australia.

Part Numbers

Order the following stock.

Part #	Description	Stocking Level
140296	Pilot Kits (NG)	B
140297	Pilot Kits (LP)	B

Warranty

Parts includes a 90-day parts warranty from the date of install.

Questions

For further information, please contact Technical Services using one of the following options:

Email: technicalservices@hennypenny.com

Call:

- U.S. and Canada: +1-800-417-8405
- Global: +1-937-456-8405

Text: +1-937-456-8405

[Live chat](#) via the Henny Penny website, extranet, or customer support website.