

Subject: FlexFusion SpaceSaver Team High Limit Bulletin

Date: 09/01/21

Region: Global

Models Affected: FlexFusion SpaceSaver Generation 1 & 2, and FlexFusion SpaceSaver Team


Summary

The FlexFusion SpaceSaver cabinet high limit P/N MM10019979 has been made obsolete starting with oven serial number 21536605. Regardless of the oven's serial number, service providers should continue to order high limit kit P/N MM202807 which now includes both a high limit and bracket.

- Ovens built before the serial number break, requires both the high limit and bracket for service repairs.
- Ovens built after the serial number break, requires a high limit only, and the bracket may be discarded.

NOTE: Previously, high limit P/N MM202807 included only a high limit and did not include a bracket.

Bracket Orientation



Part Number

Order the following part.

Part #	Description	Stocking Level
MM202807	High Limit with Bracket	A

Warranty

Kit includes a 90-day parts warranty from the date of install.

Questions

For further information, please contact Technical Services using one of the following options:

Email: technicalservices@hennypenny.com

Call:

- U.S. and Canada: +1-800-417-8405
- Global: +1-937-456-8405

Text: +1-937-456-8405

[Live chat](#) via the Henny Penny website, extranet, or customer support website.