


**Subject:** LVE 20x Split Vat High Limit Dual Thermocouple Service Pack  
**Date:** 09/03/21  
**Region:** Global  
**Models Affected:** LVE 20X Split Vat Fryers  
**Reference:** Solid State High Limit Change bulletin sent 12/1/2020, see attached.

### Summary

As referenced in the attached “Solid State High Limit Change” bulletin from 12/01/20, Henny Penny is releasing split vat high limit dual thermocouple service pack P/N 181867 for LVE 20X split vat units built after 12/2020.



**IMPORTANT:** The existing 96887 single thermocouple high limit service pack is still valid for LVE 20X full vat units built after 12/2020, because each element has two single thermocouples. Additionally, the 96887 single thermocouple high limit service pack is valid for all LVE 20X full and split vat units built before 12/2020.

### Part Numbers

For LVE 20X high limit thermocouple replacement, use the following service packs.

Part #	Description	Stocking Level
181867	High limit dual thermocouple service pack - Split vat only (After 12/2020)	A
96887	High limit single thermocouple service pack - Full and split vats (Before 12/2020)	A

### Warranty

Service packs include a 90-day parts warranty from the date of install.

### Questions

For further information, please contact Technical Services using one of the following options:

Email: [technicalservices@hennypenny.com](mailto:technicalservices@hennypenny.com)

Call:

- U.S. and Canada: +1-800-417-8405
- Global: +1-937-456-8405

Text: +1-937-456-8405

[Live chat](#) via the Henny Penny website, extranet, or customer support website.