

**Subject:** New Chamber Probe Conversion Kit P/N MM10036776

**Date:** 01/23/24

**Region:** U.S.

**Model Affected:** SpaceSaver Gen 1, FlexFusion, FlexFusion Team

---

**Summary**

A new chamber probe conversion kit P/N MM10036776 replaces the cooking cabinet sensor P/N MM10013520, which is no longer available. From Henny Penny S/N 23012446 and after, cooking cabinet sensor P/N MM10031251 is used. The conversion kit must be used for servicing.

**Procedure**

See attached service procedure.

**Part Numbers**

Order the following stock (kit) as applicable.

Model	Part #	Description	Stocking Level	Qty
- SpaceSaver Gen 1 - FlexFusion - FlexFusion Team	MM10036776	Conversion kit cooking chamber	C	1

**Warranty**

The kit includes a 90-day parts warranty from the date of install.

**Questions**

For further information, please contact Technical Services using one of the following options:

Email: [technicalservices@hennypenny.com](mailto:technicalservices@hennypenny.com)

Call:

- U.S. and Canada: +1-800-417-8405
- Global: +1-937-456-8405

Text: +1-937-456-8405

[Live chat](#) via the Henny Penny website, extranet, or customer support website.

Try our Henny Penny Service YouTube Channel: [www.youtube.com/hennypennyservice](http://www.youtube.com/hennypennyservice).